

Figure 14. Calibration Phase Transitions for Bi, Hg, and Yb
(for increasing pressure)