

ILLUSTRATIONS (Concl'd)

Figure	A-10	Punch Assembly Number 1	80
	A-11	Punch Assembly Number 2	80
	A-12	Die Assembly Interface Diagram	81

TABLES

Table	I.	Stress Distribution for 1×10^6 psi Punch Assembly	5
	II.	Stress Distribution for 3×10^6 psi Die Assembly	6
	III.	Cubic Boron Nitride Preparations	14
	IV.	Sm_2O_3 Runs	18
	V.	X-ray Diffraction Results β SmOOH	21
	VI.	X-ray Diffraction Results $\text{Sm}(\text{OH})_3$	23
	VII.	MgO Samples Sent to AFCRL	31
	VIII.	NiO Preparations	33
	IX.	Cr_2O_3 Preparations	36