

P= 0.001 T= 15000. NTOT=4.89E 14 DEBYE=5.36E-05 LAMBDA=1.93E 03 LNLMBD= 7.56
 N1=2.48287E 14 N2=2.52899E 11 N3=2.33234E 14 N4=7.52643E 12 N5=2.71852E 06

B	CM-TAU	SIG-1	SIG-2	DT-1	DT-2	LAM-1	LAM-2
0.	0.00E-01	3.89E 01	0.00E-01	1.94E-07	0.00E-01	7.21E 00	0.00E-01
500.	-2.88E 00	1.80E 00	7.01E 00	-9.19E-09	1.38E-08	7.06E-01	1.63E 00
1000.	-5.76E 00	5.78E-01	3.78E 00	-4.64E-09	3.26E-09	2.67E-01	9.82E-01
2500.	-1.44E 01	1.07E-01	1.57E 00	-1.01E-09	2.80E-10	5.17E-02	4.33E-01
5000.	-2.88E 01	2.74E-02	7.93E-01	-2.66E-10	3.67E-11	1.34E-02	2.20E-01
7500.	-4.32E 01	1.22E-02	5.30E-01	-1.20E-10	1.10E-11	5.97E-03	1.47E-01
10000.	-5.76E 01	6.90E-03	3.98E-01	-6.75E-11	4.65E-12	3.37E-03	1.11E-01
25000.	-1.44E 02	1.11E-03	1.59E-01	-1.08E-11	2.99E-13	5.40E-04	4.43E-02
50000.	-2.88E 02	2.76E-04	7.96E-02	-2.71E-12	3.74E-14	1.35E-04	2.22E-02
100000.	-5.76E 02	6.91E-05	3.98E-02	-6.78E-13	4.67E-15	3.37E-05	1.11E-02
150000.	-8.63E 02	3.07E-05	2.65E-02	-3.01E-13	1.38E-15	1.50E-05	7.38E-03

P= 0.001 T= 16000. NTOT=4.59E 14 DEBYE=5.60E-05 LAMBDA=2.15E 03 LNLMBD= 7.67
 N1=2.42577E 14 N2=9.59048E 10 N3=1.89513E 14 N4=2.65319E 13 N5=8.00634E 07

B	CM-TAU	SIG-1	SIG-2	DT-1	DT-2	LAM-1	LAM-2
0.	0.00E-01	3.86E 01	0.00E-01	2.15E-07	0.00E-01	8.00E 00	0.00E-01
500.	-2.86E 00	1.76E 00	6.83E 00	-9.84E-09	1.45E-08	7.24E-01	1.71E 00
1000.	-5.72E 00	5.69E-01	3.69E 00	-4.91E-09	3.39E-09	2.72E-01	1.03E 00
2500.	-1.43E 01	1.05E-01	1.54E 00	-1.06E-09	2.89E-10	5.24E-02	4.52E-01
5000.	-2.86E 01	2.69E-02	7.75E-01	-2.79E-10	3.79E-11	1.35E-02	2.30E-01
7500.	-4.29E 01	1.20E-02	5.18E-01	-1.25E-10	1.13E-11	6.04E-03	1.54E-01
10000.	-5.72E 01	6.78E-03	3.88E-01	-7.07E-11	4.79E-12	3.40E-03	1.15E-01
25000.	-1.43E 02	1.09E-03	1.55E-01	-1.14E-11	3.08E-13	5.46E-04	4.62E-02
50000.	-2.86E 02	2.72E-04	7.77E-02	-2.84E-12	3.85E-14	1.37E-04	2.31E-02
100000.	-5.72E 02	6.80E-05	3.89E-02	-7.10E-13	4.81E-15	3.41E-05	1.15E-02
150000.	-8.57E 02	3.02E-05	2.59E-02	-3.16E-13	1.43E-15	1.52E-05	7.70E-03

P= 0.001 T= 17000. NTOT=4.32E 14 DEBYE=5.73E-05 LAMBDA=2.33E 03 LNLMBD= 7.75
 N1=2.46524E 14 N2=3.56842E 10 N3=1.23827E 14 N4=6.13467E 13 N5=1.17153E 09

B	CM-TAU	SIG-1	SIG-2	DT-1	DT-2	LAM-1	LAM-2
0.	0.00E-01	3.63E 01	0.00E-01	2.29E-07	0.00E-01	8.59E 00	0.00E-01
500.	-2.56E 00	1.88E 00	6.80E 00	-1.05E-08	1.71E-08	7.79E-01	1.81E 00
1000.	-5.12E 00	6.26E-01	3.71E 00	-5.61E-09	4.21E-09	3.02E-01	1.10E 00
2500.	-1.28E 01	1.18E-01	1.56E 00	-1.26E-09	3.71E-10	5.96E-02	4.86E-01
5000.	-2.56E 01	3.05E-02	7.87E-01	-3.35E-10	4.90E-11	1.54E-02	2.48E-01
7500.	-3.84E 01	1.36E-02	5.26E-01	-1.50E-10	1.47E-11	6.91E-03	1.66E-01
10000.	-5.12E 01	7.69E-03	3.95E-01	-8.50E-11	6.22E-12	3.90E-03	1.24E-01
25000.	-1.28E 02	1.23E-03	1.58E-01	-1.37E-11	4.00E-13	6.25E-04	4.98E-02
50000.	-2.56E 02	3.08E-04	7.90E-02	-3.42E-12	5.00E-14	1.56E-04	2.49E-02
100000.	-5.12E 02	7.71E-05	3.95E-02	-8.54E-13	6.25E-15	3.91E-05	1.25E-02
150000.	-7.68E 02	3.43E-05	2.63E-02	-3.80E-13	1.85E-15	1.74E-05	8.31E-03

P= 0.001 T= 18000. NTOT=4.08E 14 DEBYE=5.84E-05 LAMBDA=2.52E 03 LNLMBD= 7.83
 N1=2.51131E 14 N2=1.17538E 10 N3=6.20937E 13 N4=9.45044E 13 N5=9.33224E 09

B	CM-TAU	SIG-1	SIG-2	DT-1	DT-2	LAM-1	LAM-2
0.	0.00E-01	3.51E 01	0.00E-01	2.46E-07	0.00E-01	9.26E 00	0.00E-01
500.	-2.36E 00	1.98E 00	6.82E 00	-1.12E-08	1.96E-08	8.35E-01	1.92E 00
1000.	-4.73E 00	6.73E-01	3.75E 00	-6.28E-09	5.01E-09	3.33E-01	1.17E 00
2500.	-1.18E 01	1.30E-01	1.59E 00	-1.46E-09	4.55E-10	6.69E-02	5.23E-01
5000.	-2.36E 01	3.36E-02	8.02E-01	-3.90E-10	6.05E-11	1.74E-02	2.67E-01
7500.	-3.54E 01	1.51E-02	5.36E-01	-1.76E-10	1.82E-11	7.79E-03	1.79E-01
10000.	-4.73E 01	8.49E-03	4.02E-01	-9.92E-11	7.69E-12	4.39E-03	1.34E-01
25000.	-1.18E 02	1.36E-03	1.61E-01	-1.59E-11	4.94E-13	7.05E-04	5.38E-02
50000.	-2.36E 02	3.41E-04	8.05E-02	-3.99E-12	6.18E-14	1.76E-04	2.69E-02
100000.	-4.73E 02	8.51E-05	4.02E-02	-9.97E-13	7.73E-15	4.41E-05	1.34E-02
150000.	-7.09E 02	3.78E-05	2.68E-02	-4.43E-13	2.29E-15	1.96E-05	8.96E-03

P= 0.001 T= 19000. NTOT=3.86E 14 DEBYE=6.03E-05 LAMBDA=2.74E 03 LNLMBD= 7.92
 N1=2.48831E 14 N2=3.52543E 09 N3=2.61279E 13 N4=1.11277E 14 N5=4.93428F 10

B	CM-TAU	SIG-1	SIG-2	DT-1	DT-2	LAM-1	LAM-2
0.	0.00E-01	3.55E 01	0.00E-01	2.69E-07	0.00E-01	1.02E 01	0.00E-01
500.	-2.38E 00	1.95E 00	6.76E 00	-1.19E-08	2.04E-08	8.65E-01	2.02E 00
1000.	-4.76E 00	6.64E-01	3.72E 00	-6.61E-09	5.18E-09	3.43E-01	1.23E 00
2500.	-1.19E 01	1.28E-01	1.57E 00	-1.52E-09	4.66E-10	6.84E-02	5.48E-01
5000.	-2.38E 01	3.31E-02	7.94E-01	-4.05E-10	6.19E-11	1.78E-02	2.79E-01
7500.	-3.57E 01	1.48E-02	5.31E-01	-1.82E-10	1.85E-11	7.95E-03	1.87E-01
10000.	-4.76E 01	8.35E-03	3.98E-01	-1.03E-10	7.86E-12	4.48E-03	1.40E-01
25000.	-1.19E 02	1.34E-03	1.59E-01	-1.66E-11	5.05E-13	7.20E-04	5.62E-02
50000.	-2.38E 02	3.35E-04	7.97E-02	-4.14E-12	6.32E-14	1.80E-04	2.81E-02
100000.	-4.76E 02	8.38E-05	3.99E-02	-1.04E-12	7.90E-15	4.50E-05	1.41E-02
150000.	-7.14E 02	3.72E-05	2.66E-02	-4.60E-13	2.34E-15	2.00E-05	9.37E-03

P= 0.001 T= 20000. NTOT=3.67E 14 DEBYE=6.28E-05 LAMBDA=3.01E 03 LNLMBD= 8.01
 N1=2.41202E 14 N2=1.06655E 09 N3=1.05428E 13 N4=1.15026E 14 N5=2.02736E 11

B	CM-TAU	SIG-1	SIG-2	DT-1	DT-2	LAM-1	LAM-2
0.	0.00E-01	3.70E 01	0.00E-01	2.98E-07	0.00E-01	1.13E 01	0.00E-01
500.	-2.54E 00	1.83E 00	6.62E 00	-1.27E-08	2.00E-08	8.70E-01	2.11E 00
1000.	-5.08E 00	6.16E-01	3.62E 00	-6.64E-09	4.84E-09	3.36E-01	1.27E 00
2500.	-1.27E 01	1.17E-01	1.53E 00	-1.47E-09	4.21E-10	6.54E-02	5.61E-01
5000.	-2.54E 01	3.01E-02	7.70E-01	-3.89E-10	5.55E-11	1.69E-02	2.85E-01
7500.	-3.81E 01	1.35E-02	5.14E-01	-1.75E-10	1.66E-11	7.56E-03	1.91E-01
10000.	-5.08E 01	7.59E-03	3.86E-01	-9.88E-11	7.04E-12	4.26E-03	1.43E-01
25000.	-1.27E 02	1.22E-03	1.55E-01	-1.59E-11	4.52E-13	6.84E-04	5.74E-02
50000.	-2.54E 02	3.04E-04	7.73E-02	-3.97E-12	5.65E-14	1.71E-04	2.87E-02
100000.	-5.08E 02	7.61E-05	3.86E-02	-9.92E-13	7.07E-15	4.28E-05	1.43E-02
150000.	-7.62E 02	3.38E-05	2.58E-02	-4.41E-13	2.09E-15	1.90E-05	9.57E-03

P= 0.001 T= 21000. NTOT=3.49E 14 DEBYE=6.57E-05 LAMBDA=3.30E 03 LNLMBD= 8.10
 N1=2.31752E 14 N2=3.46178E 08 N3=4.44520E 12 N4=1.12599E 14 N5=7.03285E 11

B	CM-TAU	SIG-1	SIG-2	DT-1	DT-2	LAM-1	LAM-2
0.	0.00E-01	3.88E 01	0.00E-01	3.30E-07	0.00E-01	1.25E 01	0.00E-01
500.	-2.76E 00	1.68E 00	6.45E 00	-1.33E-08	1.90E-08	8.62E-01	2.19E 00
1000.	-5.52E 00	5.59E-01	3.51E 00	-6.52E-09	4.35E-09	3.21E-01	1.30E 00
2500.	-1.38E 01	1.04E-01	1.47E 00	-1.39E-09	3.64E-10	6.10E-02	5.68E-01
5000.	-2.76E 01	2.67E-02	7.40E-01	-3.63E-10	4.76E-11	1.57E-02	2.88E-01
7500.	-4.14E 01	1.19E-02	4.94E-01	-1.63E-10	1.42E-11	7.01E-03	1.93E-01
10000.	-5.52E 01	6.71E-03	3.71E-01	-9.19E-11	6.02E-12	3.95E-03	1.45E-01
25000.	-1.38E 02	1.08E-03	1.49E-01	-1.48E-11	3.86E-13	6.33E-04	5.79E-02
50000.	-2.76E 02	2.69E-04	7.43E-02	-3.69E-12	4.83E-14	1.58E-04	2.89E-02
100000.	-5.52E 02	6.73E-05	3.71E-02	-9.23E-13	6.04E-15	3.96E-05	1.45E-02
150000.	-8.28E 02	2.99E-05	2.48E-02	-4.10E-13	1.79E-15	1.76E-05	9.65E-03

P= 0.001 T= 22000. NTOT=3.34E 14 DEBYE=6.86E-05 LAMBDA=3.61E 03 LNLMBD= 8.19
 N1=2.22442E 14 N2=1.21729E 08 N3=2.03142E 12 N4=1.07010E 14 N5=2.13030E 12

B	CM-TAU	SIG-1	SIG-2	DT-1	DT-2	LAM-1	LAM-2
0.	0.00E-01	4.07E 01	0.00E-01	3.64E-07	0.00E-01	1.38E 01	0.00E-01
500.	-3.00E 00	1.54E 00	6.26E 00	-1.38E-08	1.78E-08	8.48E-01	2.26E 00
1000.	-5.99E 00	5.05E-01	3.39E 00	-6.33E-09	3.88E-09	3.05E-01	1.33E 00
2500.	-1.50E 01	9.22E-02	1.41E 00	-1.30E-09	3.13E-10	5.66E-02	5.73E-01
5000.	-3.00E 01	2.36E-02	7.11E-01	-3.37E-10	4.07E-11	1.45E-02	2.90E-01
7500.	-4.50E 01	1.05E-02	4.75E-01	-1.51E-10	1.21E-11	6.47E-03	1.94E-01
10000.	-5.99E 01	5.93E-03	3.56E-01	-8.52E-11	5.13E-12	3.65E-03	1.45E-01
25000.	-1.50E 02	9.51E-04	1.43E-01	-1.37E-11	3.29E-13	5.85E-04	5.82E-02
50000.	-3.00E 02	2.38E-04	7.13E-02	-3.42E-12	4.12E-14	1.46E-04	2.91E-02
100000.	-5.99E 02	5.95E-05	3.56E-02	-8.55E-13	5.15E-15	3.66E-05	1.46E-02
150000.	-8.99E 02	2.64E-05	2.38E-02	-3.80E-13	1.53E-15	1.62E-05	9.70E-03