



Fig. 14. Plutonium-rich regions of the (a) Pu-Al, (b) Pu-Zn, and (c) Pu-Ce phase diagrams.

atm *no* delta phase can be formed regardless of temperature. As can be seen in Table II, a delta-stabilized alloy containing 4.5 a/o Al should transform reversibly from delta to alpha at 10,200 atm and a delta-stabilized alloy containing 7.1 a/o Ce transforms reversibly from delta to beta at 3800 atm. These reversible transformation pressures increase with increasing alloying contents (see Fig. 8). Thus, the addition of aluminum or cerium has the effect of extending the delta-phase field with respect to pressure, similar to the effect produced by these alloy additions in extending the delta-phase field with respect to temperature [see Figs. 14(a) and 14(c)]. The stability of beta-phase

Pu-Ce alloys after compression suggests that cerium is probably more soluble in beta than in the gamma or alpha phases.

The Pu-Zn phase diagram shows a eutectoidal decomposition of delta phase into gamma phase plus PuZn_2 at about 235–243°C, and alpha phase plus PuZn_2 corresponds to the equilibrium state of decomposed alloys at room temperature⁶ [see Fig. 14(b)]. Delta-stabilized Pu-Zn alloys are, therefore, actually metastable at room temperature and should transform under pressure to a more stable state. All delta-phase Pu-Zn alloys studied did transform under compression, substantially in agreement with this Pu-Zn phase diagram.

Acknowledgments

The authors are grateful to Miss Janet Clark for making the metallographic examinations, to F. E. Colvin and C. E. Westley for their assistance with the experiments and calculations, and to V. O. Struebing and P. G. McCrossen for preparing the alloys. In addition, the authors also wish to thank the other members of the Los Alamos plutonium chemistry and metallurgy groups whose services contributed to this work. Lastly, the authors express their appreciation to F. W. Schonfeld and D. S. Hughes for their interest and helpful suggestions.

References

1. H. L. Laquer, LAMD-1204, 1953 (Secret). (Not available.)
2. P. W. Bridgman, "Compression and the α - β Phase Transformation of Plutonium," *J. Appl. Phys.* **30**, 214 (1959).
3. D. S. Hughes, GMX-6-308, 1956 (Secret). (Not available.)
4. P. W. Bridgman, *The Physics of High Pressures*, 2nd ed., Bell and Sons, London, 1952.
5. A. S. Coffinberry, F. W. Schonfeld, E. M. Cramer, W. N. Miner, F. H. Ellinger, R. O. Elliott, and V. O. Struebing, "The Physical Metallurgy of Plutonium and Its Alloys," *Second United Nations International Conference on the Peaceful Uses of Atomic Energy, Geneva*, 1958. Paper withdrawn.
6. E. M. Cramer, F. H. Ellinger, and C. C. Land, "Plutonium-Zinc Phase Diagram," this volume, p. 169.
7. F. H. Ellinger, C. C. Land, and E. M. Cramer, "Plutonium-Cerium Phase Diagram," this volume, p. 149.
8. M. B. Waldron, J. Garstone, J. A. Lee, P. G. Mardon, J. A. C. Marples, D. M. Poole, and G. K. Williamson, "The Physical Metallurgy of Plutonium," *Second United Nations International Conference on the Peaceful Uses of Atomic Energy, Geneva*, 1958, Paper No. 71.
9. A. A. Bochvar, S. T. Konobeevsky, V. I. Kutaitsev, T. S. Menshikova, and N. T. Chebotarev, "Interaction between Plutonium and Other Metals in Connection with Their Arrangements in Mendeleev's Periodic Table," *Second United Nations Conference on the Peaceful Uses of Atomic Energy, Geneva*, 1958, Paper No. 2197.