



FIG. 1. Schematic diagram of the general arrangement of the apparatus:

- | | |
|--|----------------------------------|
| 1, piston of hydraulic press; | 8, test piece; |
| 2-5, detail of the device for measuring displacement of spindle; | 9, fixed obturator; |
| 6, high pressure chamber; | 10, electric leads; |
| 7, contact resistance; | 11, spindle; |
| | 12, connecting collar; |
| | 13, cylinder of hydraulic press. |