

(A T H letter head)

30 April, 1979


Quality Measurement Systems, Inc.
2555 Baird Road
Penfield, New York 14526

Sirs:

At the L.A. Tool Show in April, H.T. Hall spoke with your representative about a problem in the y-axis of our Model 500 Digital Readout System (Ser. No. 1156--1975). From the symptoms described, he analyzed the problem as lamp intensity attenuation due to lamp aging, and sent us three replacement lamp assemblies, gratis, for which we thank you.

Our instruction manual, however, does not contain instructions for performing the replacement--we understand that a circuit requires adjustment or balancing. Could you please send us these instructions, and perhaps an electrical schematic of the reader head unit?

Respectfully,



H. Tracy Hall, Jr.
Vice-President

(ATH Inc letter head)

30 April, 1979

Cincinnati-Milacron Co.
Service Administration Dept.
4701 Marburg Avenue
Cincinnati, Ohio 45209

Sirs:

Would you please quote us price and availability/delivery for the following replacement parts for our Cincinnati No. 1-18 Plain Automatic Milling Machine (Ser. No. 2F1P1K-136, ca. 1955) (Part numbers obtained from Parts and Service Manual Publication No. M-1196-3)

<u>Qty.</u>	<u>Cat. Key No.</u>	<u>Part Number</u>	<u>Name of Part</u>
1	2FC-25	99923	Bolt--Arbor Draw-In , <u>Type "B"</u>
1	2FC-26	70058	Nut-Arbor Draw-In Bolt "
1	2FC-27	70059	Head-Arbor Draw-In Bolt "
1	2FC-21	4039	Bronze Bushing--Arbor Support adjusting, <u>Type "B"</u>
1	2FC-20	4040	Nut
2	2FC-12	4078	Disc (Window)-Oil Gauge

Respectfully,

H. Tracy Hall, Jr.

H. Tracy Hall, Jr.
Vice-President