

at A and B in Figure 14 and is shown in Figure 15(a) and (b) for the  $\{11\bar{2}0\}$  and  $(\bar{1}010)$  surfaces. Also seen in Figure 15(a) are  $\{10\bar{1}2\}$  twins and basal slip lines. The single set of pyramidal slip lines seen in Figure 15(a) matched the  $\{11\bar{2}2\}$  traces expected for this surface. The slip lines observed in Figure 15(b) also matched the  $(11\bar{2}2)$  traces expected for this surface.

Electron transmission microscopy studies did not reveal dislocations with non-basal Burgers vectors. Micrographs were not available at the time of this report.

Submitted by:

*Nobuo Inoue*

N. Inoue  
Principal Scientist

*V. Damiano*

V. Damiano  
Principal Scientist

*J. Hanafee*

J. Hanafee  
Senior Research Metallurgist

*G. London*

G. London, Manager  
Special Projects Laboratory

*H. Conrad*

H. Conrad, Technical Director  
Materials Science and  
Engineering Department