

PENETRATION PHENOMENA

Chronological Listing

<u>Year</u>	<u>Reference number(s)</u>					
1958	3002	3039	3044	3045	3046	3047
1957	3001	3005	3006	3007	3040	3043
1956	3003	3004	3008	3032	3038	
1955	3013	3014	3030	3031	3041	3042
1954	3016	3028				
1953	3012	3026	3027	3029		
1952	3019					
1951	3009	3021	3022	3023	3025	
1950	3010					
1949	3015	3024				
1948	3011					
1947						
1946						
1945	2017					
1944	3033	3034	3036			
1943						
1942	3037					
1941	3018					
1939	3035					
1927	3020					

BEHAVIOR OF MATERIALS AT HIGH-STRAIN RATES
(1200-1299)

Subtopic

Time delay for yielding.