



Fig. 2



(a)



(b)

Pressure-induced dislocations sub-structures observed in the vicinity of second-phase particles in tungsten after pressurization to 40 kilobars: (a) 0.9 vol. % ThO_2 alloy; (b) 1.4 vol. % HfC alloy.