


Fig. 2



(a)



(b)

Pressure-induced dislocation sub-structures observed in the vicinity of second-phase particles in tungsten after pressurization to 40 kilobars: (a) 0.9 vol. %  $\text{ThO}_2$  alloy; (b) 1.4 vol. %  $\text{HfC}$  alloy.

4.1. T  
tun-  
val-  
tho-  
stil-  
vie-  
obs-  
str-  
pre-  
rec-  
ex-  
He-  
co-  
sit-

(F  
su-  
le-  
ir-  
et-  
ti-  
f-  
s-  
e-  
i-  
;