

FIG. 23 EFFECTS OF CASEHARDENING AND NOTCH-WALL THICKNESS ON FAILURE OF 3/8" O.D. (1/8" I.D.) TUBES SUBJECTED TO STATIC LOADS




FIG. 24 EFFECTS OF CASEHARDENING AND NOTCH-WALL THICKNESS ON FAILURE OF 3/8"O.D. (1/8"I.D.) TUBES SUBJECTED TO DYNAMIC LOADS